

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Dutch Creek Work Station, Bunkhouse (Bldg 1179)
Boise National Forest
Atlanta Vicinity
Elmore County
Idaho

HABS No. ID-62

HABS

ID,

20-ATLA.Y,

2A -

J. Ceronie and Marie Neubauer, Photographers June 1984

ID-62-1 3/4 VIEW LOOKING SOUTHWEST

ID-62-2 3/4 VIEW LOOKING NORTHEAST

ID-62-3 SOUTH SIDE

ID-62-4 INTERIOR VIEW OF MAIN ROOM LOOKING NORTHEAST

ID-62-5 INTERIOR VIEW OF SLEEPING QUARTERS LOOKING NORTH-NORTHEAST